



Ernitec SX3 firmware

Release notes

Version 2016 0419 NSP

Important Information

Before proceeding, please read and observe all instructions and warnings in this manual and general procedure regarding upgrading Ernitec firmware and software.

Retain this manual with the original bill of sale for future reference and, if necessary, warranty service.

When upgrading or downgrading your device, please make a reboot of the device prior to the actual update.

Check for missing or damaged items. If any item is missing, or if damage is evident, **DO NOT INSTALL OR OPERATE THIS PRODUCT**. Contact your dealer for assistance

Ernitec Firmware Release Note

Update software/firmware Version

ER 2016 0419 NSP

Release date

21.07.2016

Applied Models

Mercury SX 332IR

Mercury SX 333IR

Mercury SX 334IR

Bug fix:

1. First Release

Improvement:

1. UWDR 25pfs option all versions.
2. Mercury SX 334IR 3MP resolution 2048*1536 @ 25fps
3. Mercury SX 324IR Higher Resolutions 2688*1512 @ 25fps
4. Mercury SX 324IR Higher Frame Rate 2560*1440 @ 25fps

New features:

1. UWDR Gamma Feature high, med, low
2. IR Compensation on, off