



Ernitec SX firmware

Release notes

Version 2017 0118 NSP

Important Information

Before proceeding, please read and observe all instructions and warnings in this manual and general procedure regarding upgrading Ernitec firmware and software.

Retain this manual with the original bill of sale for future reference and, if necessary, warranty service.

When upgrading or downgrading your device, please make a reboot of the device prior to the actual update.

Check for missing or damaged items. If any item is missing, or if damage is evident, **DO NOT INSTALL OR OPERATE THIS PRODUCT**. Contact your dealer for assistance

Ernitec Firmware Release Note

Update software/firmware

Version er20170118NSP

Release date

03/02/2017

Applied Models

Mercury SX 342IR

Mercury SX 343IR

Mercury SX 344IR

Bug fix:

1. All Versions can now be imported to EasyView VMS using OnVif Driver

Improvement:

1. All Mercury SX4 models now come with MJPEG as standard stream
2. New Ernitec skin for camera menu system
3. New IR LED 45M Range
4. SX4 Now with 2.8-12mm Lens
5. Real time in all resolutions

New features:

1. UWDR Gamma Feature high, med, low
2. IR Compensation on, off