



Ernitec SX firmware

Release notes

Version 2016 1116 NSP

Important Information

Before proceeding, please read and observe all instructions and warnings in this manual and general procedure regarding upgrading Ernitec firmware and software.

Retain this manual with the original bill of sale for future reference and, if necessary, warranty service.

When upgrading or downgrading your device, please make a reboot of the device prior to the actual update.

Check for missing or damaged items. If any item is missing, or if damage is evident, **DO NOT INSTALL OR OPERATE THIS PRODUCT**. Contact your dealer for assistance

Ernitec Firmware Release Note

Update software/firmware

Version er201601116NSP

Release date

09/01/2017

Applied Models

Mercury SX 342R

Mercury SX 343IR

Mercury SX 344IR

Bug fix:

1. All Versions can now be imported to EasyView VMS using OnVif Driver

Improvement:

1. UWDR 25pfs option all versions.
2. Mercury SX 344IR 3MP resolution 2048*1536 @ 25fps
3. Mercury SX 344IR Higher Resolutions 2688*1512 @ 25fps
4. Mercury SX 344IR Higher Frame Rate 2560*1440 @ 25fps
5. All Mercury SX4 models now include a 2.8-12mm Lens

New features:

1. UWDR Gamma Feature high, med, low
2. IR Compensation on, off