



Connection of BDR-51X




Connection of BDR-575




* Cable termination:
Enable LK1 on interface board

Connection of BDR-55X




Connection of ICU




* Cable termination:
120 ohm resistor across +/-


Example on combination



Example on combination



Example on combination



* Cable termination:
Enable LK1 on interface board

Fig. 3