



# **Ernitec PX firmware**

**Release notes**

**Version 2016 0728 NSP**

## **Important Information**

Before proceeding, please read and observe all instructions and warnings in this manual and general procedure regarding upgrading Ernitec firmware and software.

Retain this manual with the original bill of sale for future reference and, if necessary, warranty service.

When upgrading or downgrading your device, please make a reboot of the device prior to the actual update.

Check for missing or damaged items. If any item is missing, or if damage is evident, **DO NOT INSTALL OR OPERATE THIS PRODUCT**. Contact your dealer for assistance

## Ernitec Firmware Release Note

### **Update software/firmware Version**

er20160728NSP

### **Release date**

01.09.2017

### **Applied Models**

Mercury SX 332IR

Mercury SX 333IR

Mercury SX 334IR

---

### **Bug fix:**

1. All Versions can now be imported to EasyView VMS using OnVif Driver

### **Improvement:**

1. UWDR 25pfs option all versions.
2. Mercury SX 334IR 3MP resolution 2048\*1536 @ 25fps
3. Mercury SX 324IR Higher Resolutions 2688\*1512 @ 25fps
4. Mercury SX 324IR Higher Frame Rate 2560\*1440 @ 25fps

### **New features:**

1. UWDR Gamma Feature high, med, low
2. IR Compensation on, off